

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
A	8-37		AR/LR ADDED TO DOWN MAIN HOME. INTERLINKING AMENDED.	
			DOWN SIDINGS (NEW SIDINGS) BRACKET STARTING SIGNAL REPLACED BY SINGLE DISC.	C. 7-52
B	12-52		DOWN RELIEF INNER HOME BANNER REPEAT SIGNALS RECOVERED	18-1-53
C	2-53		UP BRANCH SIDING RECOVERED.	C.O.
			R. I. SIGNAL UPSIDINGS TO UP BRANCH OR DOWN RELIEF OR DOWN MAIN REPOSITIONED 10 YDS FURTHER FROM S.B.	C. 3-55
D	8-56		DOWN MAIN INNER HOME BRACKET SIGNAL RENEWED. (21/4097)	22-7-56
E	1-58		T.C. PROVIDED 1/L/O BAR THROUGH CONNECTION IN UP MAIN (37T) (22/7663)	20-4-58
F	9-60		DOWN RELIEF INNER HOMES BKT; DOWN BRANCH INNER HOME R.I.; DOWN RELIEF HOME; UPSDG STG & FROM N°2 & N°3 BRANCH SDGS STG SIGNALS RENEWED. (21/6148)	4-1-61
G	6-62		UP BRANCH STARTING SIGNAL RENEWED & UP BRANCH ADVANCED STARTING SIGNAL RECOVERED. (21/9937)	22-7-62
H	3-63		UP MAIN & UP RELIEF HOME WITH LOWER DISTANTS RENEWED AS BRACKET SIGNAL. (21/9937/3)	9-6-63
I	4-63		CATCH POINT IN N°s 2 & 3 BRANCH SDGS RECOVERED & ONE DISC PROVIDED 1/L/O THROUGH (28/32 52/3)	9-6-63

LLANHILLETH MIDDLE

RECORD OF AMENDMENTS

S1331 / 1