

SERIAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			CLOSURE OF HAMPTON ROW S.B. ADDITIONAL DOWN HOME & TC IN REAR	3.4. 1910
S715 724 725			TEMP. INTERLACING AT WEST END FOR VIADUCT WORK. TEMP. NED UP HOME. ENGINEERS G.F. PROVIDED.	5.2. 1911
S726			INTERLACING TRANSFERRED TO DOWN LINE UNTIL VIADUCT WORK COMPLETED	5.3. 1911 to 9.4. 1911
			TC IN REAR OF UP HOME	by 1915
			UP DETONATOR PROVIDED	by 8.1915
			DOWN DETONATOR PROVIDED	

BATH SPA

RECORD OF AMENDMENTS

S 574 /1/1

SER -IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
S 1392			ATC RAMPS PROVIDED	8.1930
S 1964			OPENING OF BATHAMPTON WEST S.B.	1. 11. 1942
S 2110			UP MAIN INTERMEDIATE DISTANT RENEWED. LOCKING ALTERATION. 43 MADE SPARE ?	16.6.1946
S 2137			'RA' INDICATORS FOR DOWN LINE PROVIDED	1.4. 1947

BATH SPA

RECORD OF AMENDMENTS

S 574 /1/2

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
A 52332			CLOSURE OF BATHAMPTON WEST.	
B	5.1959		UP MAIN C.O. SIGNAL 43 PROVIDED.	16.9.1956
C	7.1959	SP 59/45	25T PROVIDED	
D	8.1959		PREPARATORY WORK 11d/w PLATFORM LENGTHENING. SIDINGS RECOVERED. LEVERS 18.19.20.21.27.28.29.30 MADE SPARE.	1.1960
E	11.1959		SIGNAL 40 RENEWED ON UP SIDE AT 93X. 4OR PROVIDED	
G/F	1.1961		SIGNAL 4 RENEWED ON DOWN SIDE	
H	10.1962		NO 2 MIDDLE SIDING RECOVERED.	
K			DN MAIN ADV'CD STARTING RECOVERED. RA INDICATOR RECOVERED. WEST + OVER. SC & P.	5.7.1964
J			SIGNALS 3 & 38 BLOCK RELEASED	
L			MAINS + OVER (WEST) RECOVERED	7.11.1965
M			UP BAY & MAINS + OVER RECOVERED	31.3.1967
N			MIDDLE SIDING RECOVERED. MAN + OVER REINSTATED	4.1967

BATH SPA

RECORD OF AMENDMENTS

S 574 /1/3