


New Tredegar

Spaces - 3.4.5.7.8.9.12.13.14.15.16.17.



NOTES

- ① Derived from locking chart and notice for Singling line. No 29 signal NB shown on notice. ~~it~~ section it was added afterwards. (Shown rubbed out on 2319/2 on up side of single line)
- ② Locking table to be checked by MRLI.

* ~~bob~~ is "New" on page 2!

* Notice No 127 DML starting has been fixed on Down side at 109 yds. not as shown in Notice No 121.

Distances from S2319/12 RE-TRAZED 23.9.49. (No 1 renewed on up side 2/10/49.)