

1⁰
UP
MAIN
DISTANT
4
3
2

2⁰
UP
MAIN
HOME

3⁰
UP
MAIN
INNER
HOME

4⁰
UP
MAIN
START'G
LINE
CLEAR

5⁰
DISC
FOR
No. 6
6

6
MAIN
* OVER

7
DISC
FOR
No. 6
6

8
DISC
FOR
No. 9
9

9
MAIN
* OVER

10
DISC
FOR
No. 9
9

11
DISC
FOR
No. 12
12

12
UP
MAIN
SIDINGS

13
DISC
FOR
No. 12
12

14⁰
DOWN
MAIN
ADV'CD
START'G
LINE
CLEAR

15⁰
DOWN
MAIN
START'G

16⁰
DOWN
MAIN
HOME

17⁰
DOWN
MAIN
DISTANT
14
15
16

UP
MAIN
DETONATORS
OFF
ON

DOWN
MAIN
DETONATORS
OFF
ON

INSPECTOR WILLIAMS
WORCESTER N/D
O = NEW LEADS REQ'D ASAP

1
UP
MAIN
DETONATORS
OFF
ON

14
DOWN
MAIN
DETONATORS
OFF
ON

INSPECTOR HATTER
WORCESTER! 16.4.1931.

BLACKPOLE SIDINGS

S 2598/7/

1
UP
MAIN
DISTANT
4
3

3
UP
MAIN
HOME

15
DOWN
MAIN
STARTING
LINE
CLEAR

17
DOWN
MAIN
DISTANT
15
16

IVORINES & CASTINGS
INSPECTOR ABEL
WORCESTER
(BOOK 13 p. 65!)
40/4375

2
UP
MAIN
DISTANT
4
3

3
UP
MAIN
HOME

17
DOWN
MAIN
DISTANT
15
16

INSPECTOR HATTER
O/No. 2273
4.3.1931.

ELECTRICAL REPEATERS		
TYPE	FLAG	Nos
ARM	1	15.17.
SLOT	4	1
LIGHT	10	15.17.

R282

BLACKPOLE SIDINGS	
	52598/7