

A	CO-ACTING ARM PROVIDED BELOW DOWN RELIEF INNER HOME.	Nov 57	12.7. 62
B	UP MAIN DISTANT RENEWED. AS 2 ASPECT C/L.	MAY 58	
C	UP MAIN & UP RELIEF DETONATORS PROVIDED.	SEPT 59	
D	EPRS PROVIDED.	DEC 60	
E	DN MAIN & DN PLATFORM STG. BKT. SIG. RENEWED.	MAY 61	
F	ARM PROVING & N/P DETECTION IN MOTOR POINTS UP RELIEF TO UP MAIN.	JUNE 61	
G	LEVERS BOLTED I/C/W RECOVERY OF POINTS UP RELIEF TO SDGS. AND ASSOC. DISCS.	OCT 63	25. 10. 63.
H	ALTERATIONS I/C/W CLOSURE OF DENHAM EAST S.B.	DEC 65	14.12. 65
J	UP MN. HOME, UP MN. INNER HOME AND DN MN. ADVCD. STARTING SIGS MOVED FURTHER FROM S.B.	29.9. 70	4.10 70
K	B.R A.W.S PROVIDED.	AUG 71	
L	PROVIDED IN DETECTION CIRCUITS FOR ALL MOTOR OPERATED POINTS		
M	ALTERATIONS I/C/W RECOVERY OF UP RELIEF WEST & SOUTH RUISLIP LEVERS BOLTED.	DEC 73	9.12. 73
R	ABOLITION OF DENHAM S.B.	30.11 74	
S	RECOVERY OF REDUNDANT ASSETS.		

WEST RUISLIP

SERIAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
	AUTH. 7.1926		SMALL 2-LEVER FRAME WORKING DOWN MAIN & RELIEF DETONATORS PROVIDED	
	AUTH. 1.1928		3-SHOT DETONATOR PLACER PROVIDED AT DOWN RELIEF STARTING.	
			A.T.C. PROVIDED FOR UP & DOWN DISTANTS	
	AUTH. 7.1935		ADDITIONAL DISCS	
			DOWN SPDR & LEAD TO A.M. SIDINGS PROVIDED.	
			UP MAIN OUTER HOME ADDED: UP MN DISTANT RENEWED FURTHER OUT & NUMBERED '6'. UP RELIEF TO MAIN FACING CONN. & SIGNALS ADDED (NOTICE E5)	1942 12.7.1942
			UP SIDINGS & G.F. ADDED.	
			DOWN MAIN & RELIEF DISTANT SIGNALS RENEWED ON GANTRY AT 1570 YDS (NOTICE E9)	17.6.1945
			GOVT SIDINGS, GF & CONNECTIONS RECOVERED	
			S.B. RENAMED WEST RUISLIP DOWN MAIN STARTING SIGNAL MOVED.	30.6.1947
	12.1949		F.P.L. 18 LOCKED REVERSE BY EXISTING 39Y.	
B			UP MAIN DISTANT RENEWED AS C/L AT 2251X	34.1959

see notices

8.7.47

11.7.47

8.3.49



RUISLIP & ICKENHAM

RECORD OF AMENDMENTS

S 63 / 1 / 2

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
C	9.1959		SMALL 2-LEVER FRAME WORKING UP MAIN & RELIEF DETONATORS PROVIDED	
D			ELNS PROVIDED	
E	5.1961		DN MAIN & PLATFORM STARTING COMBINED AS BRACKET & DISC.	3.1962
F	6.1961		ARM PROVING & N.P. DETECTION IN MOTOR POINTS	
A	11.1957		CO-ACTING ARM ADDED TO DN RELIEF INNER HOME	12.7.1962
			DOWN DISTANTS RENEWED AS BRACKET	*
			DOWN HOMES RENEWED AS BRACKET	*
G			BAY SIDING RECOVERED	25.10.1963
H			11CW CLOSURE OF DENHAM EAST SB	14.12.1965
-	-		11CW CLOSURE OF NORTHOLT JCN WEST	17.7.1966
J			LAYOUT ALTERED (SEE NOTICE 1.XO 115)	24.10.1970
K	8.1971		BR AWS 1140 ATC	
L			ALTERATION TO E.D.	
M			RECOVERY OF UP RELIEF TO NORTHOLT JCN	9.12.1973

* SEQUENCE UNKNOWN

RUISLIP & ICKENHAM

RECORD OF AMENDMENTS

S 63/1/3

SER -IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
R			11dW CLOSURE OF DENHAM S.B.	
S			UP SIDINGS RECOVERED	5.3. 1978

			RUISLIP & ICKENHAM	
			RECORD OF AMENDMENTS	S 63 /1/4