

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
12			NEW UP RELIEF LINE & UP BAY	17.1.1932
14			NEW DOWN RELIEF LINE FROM CREECH JCN INTO USE	18.1.1932
35			COMPLETION OF QUADRUPLING THROUGH STATION	7.2.1932
108			CLOSURE OF EAST STATION BOX. ADDITIONAL CONNECTIONS PROVIDED LOOP INDICATOR PROVIDED	10.4.1932
A	4.8.32		HAND PLUNGERS REMOVED	
236			3FT ARMS & 4" LIGHTS ON SIGNALS TO AND FROM BAY LINES	18.9.34.
207			CLEAR/OCCUPIED INDICATOR FOR DOWN GOODS 1/40 EXISTING LOOP INDICATOR	29.6.38.
B	11.7.40		STICK RELAYS ADDED	
309			LOOP INDICATOR RECOVERED	20.6.43
C	3.54	S53/ 177	EAST PROVIDED. TRIPLE DISC 46/47/50 1/40 DOUBLE & SINGLE DISCS	

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
D	12.54		WB & S Co LOCK & CIRCUIT CONTROLLER PROVIDED	
E	4.56		UP RELIEF PLATFORM REPEATER PROVIDED	
F		555/ 374	GOODS LINE SPUR RECOVERED. LEVERS 98 & 115 MADE SPARE	11.56
G			UP MAIN & RELIEF OUTER ADVANCED STARTINGS RENEWED AS 3-ASPECT AT 1228x. 22T & 25T EXTENDED BY 280x. ATC PROVIDED	23.12.57
H			DOWN MAIN & RELIEF DISTANTS RENEWED AS 2-ASPECT BRACKET AT 2194x. ATC RAMPS MOVED OUT (24.12.57?)	
I	6.58		FPL BAR 104 RECOVERED. 104(R)L PROVIDED	c. 2.60
J	4.59		TCS 1/40 FPL BARS (FPL 104 c 2.1960)	
-			DN MAIN INNER HOMES BRACKET RENEWED & REDUCED TO 30' 6"	2.61.
			DN RELIEF INNER HOMES BRACKET RENEWED & REDUCED TO 31' 6"	
-			DOLLS ON UP HOMES GANTRY RENEWED	5.61.
K			R.I. FROM INTERCHANGE SIDING OR SPUR TO DOWN BAYS RENEWED (AS DISCS?)	27.7.61.
			DN RELIEF ADV'D STARTING BRACKET RENEWED & INCREASED TO 31'	23.7.61
L	8.61		DISCS 42/43 REPOSITIONED ON UP SIDE OF UP RELIEF	
270 M			SIGNALS 75 RENEWED AS ELEVATED DISC	5.6. 62
N			POINTS 71 & DISC 72 RECOVERED.	17.5. 62

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
O			XOVER 108 & ASSOCIATED DISCS RECOVERED	16.12.62
R			EAST LOOP DN GOODS HOME RENEWED	16.6.63
			DOWN MAIN STARTINGS & UP MAIN INNER HOMES COMBINED AS A-DOLL BRACKET. UP RELIEF INNER HOME RENEWED AS R.H. BRACKET (R.H.DOLL NOT IN USE. TCS ADJUSTED)	23.6.63
Q			DOWN MAIN & RELIEF HOMES RENEWED AS BRACKET WITH ADDITIONAL DISTANTS FOR WEST STATION. UP BAY STARTING RENEWED. UP GOODS STARTING RENEWED WITHOUT RINGED ARM	14.7.63
P			CLOSURE OF TAUNTON EAST LOOP SB.	20-24.7.63
S			DISC BACKING UP RELIEF OR TO UP MAIN TO HOLD UP RELIEF TO MAIN FACING POINTS B/W. BACK LOCK CIRCUIT ON UP MAIN STARTINGS AMENDED. JN NAMING CORRECTED	28.7.63
T	8.63		LOCK CONTROLS ON UP MAIN/UP GOODS POINTS AMENDED	
V			UP MAIN TO RELIEF FACING (EAST) POINTS RECOVERED. UP MAIN STARTING RENEWED.	19.1.65
U			CONNECTION DN RELIEF TO BAYS RECOVERED. NEW DISC FROM BAY LINES TO INTERCHANGE SIDING.	29.4.65
W			CLOSURE OF TAUNTON WEST LOOP SB.	20.6.65
X			UP RELIEF TO MAIN FACING (EAST) POINTS RECOVERED.	23.7.65
Y			1/dw REDDING EAST JCN G.F. TO HPS	30.3.66
Z	4.66		1/dw RECOVERY OF CREECH JCN UP HOMES	

TAUNTON EAST JCN

RECORD OF AMENDMENTS

S

/1

✓ Y	ALTERATIONS I/C/W REDUCING EAST JCN G.F TO H.P.s.	4.2 66	30.3 66	AQ	ALTERATIONS I C W TAUNTON RELIEF ROAD BRIDGE (162M 4S ¹ / ₂ CH)			LOCKING SKETCH 31.3 82
? Z	ALT. I/C/W RECOVERY OF CREECH JCN. U.M. & U.R. HOME SIGS.	APRIL 66		AR	RECOVERY OF CONNECTIONS BETWEEN UP RELIEF AND WEST SIDINGS. LEVERS BOLTED.			10.82 1.8.8 RAC
✓ AA	ALT. I/C/W RECOVERY OF CREECH JCN. S.B	JUN 66	23.10 66					
✓ AB	ALT. I/C/W RECOVERY OF SIDING. LEVER BOLTED.	JUN 68						
✓ AC	FACING X-OVER D.M + D.R REBONDED I C W ENG'RS. RELAYING. (A14ST & A137T)	OCT 68	6.10 68					
✓ AD	FACING X-OVER U.M - U.R REBONDED I C W ENG'RS. RELAYING. (18T & B10T.)	DEC 68	20.4 69					
✓ AE	C68T AND 146T CONVERTED TO ASTER TRACKS I/C/W CWR	APR 69	1.6 69					
✓ AF	WJ U.M & U.R DISTANTS MADE DISTANTS FOR W. STN. & E. JCN. I/C/W CLOSURE OF W JCN S.B	DEC 70	6.12 70					
✓ AG	RE-WIRE OF SIGNAL BOX.							
✓ AH	INDUCTORS PROVIDED.	JULY 74						
✓ AJ	AMEND DOWN RELIEF LINE CLEAR RELEASE.	MAR 75						
✓ AK	H W POINTS I LO S.G.E.R CO. ARM PROVING PROVIDED.	22.6. 75						
✓ AL	AMENDED I C W RECOVER- IES AT TAUNTON WEST STA.	MAY 76						
✓ AM	CABLING I/L/O OVERHEAD WIRES.	MAY 78						
✓ AN	ALTERATIONS I.C.W POWER OPERATIONS OF No 45 POINTS.							2/80 (LOCKING SKETCH)
✓ AO	TRACK CIRCUIT PROVIDED I/L/O UP GOODS LOOP SAFETY F.P.L BAR.							
✓ AP	AMENDED I C W HABD RENEWELS ON DBL AND PROVISION ON DCC							

TAUNTON EAST JCN

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			CLOSURE OF CREECH JCN S.B.	23.10. 66
	6.68		SIDING RECOVERED, LEVER BOLTED	
			A145T & A137T REBONDED 1/d/W RELAYING	6.10. 68
			18T & B10T REBONDED 1/d/W RELAYING	20.4. 69.
			C68T & 146T CONVERTED TO ASTERS	1. 6. 69.

TAUNTON EAST JCN

RECORD OF AMENDMENTS

S /1