

ROSKEAR JUNCTION

Y ^{SH}	R ^{W/B} ^{SH}		R ^{SH}	B
<u>2</u>	<u>4</u>	<u>7</u>	<u>14</u>	<u>15</u>
UP	UP	UP	SHUNT	<u>MAINS</u>
MAIN	MAIN	MAIN	AT	+OVER
DISTANT	<u>HOME</u>	DETONATORS	<u>15B</u>	
<u>4</u>	<u>16</u>	<u>OFF</u>	<u>16</u>	
		ON	<u>15</u>	

BL	B	R *		R ^{W/B} ^{SH}
<u>16</u>	<u>17</u>	<u>18</u>	<u>19</u>	<u>23</u>
F.P.L	UP	NORTH	DOWN	DOWN
FOR	MAIN	ROSKEAR	MAIN	MAIN
ITA	<u>FACING</u>	BRANCH	DETONATORS	STARTING
	NORTH	TO	<u>OFF</u>	
	ROSKEAR	DOWN	ON	
	BRANCH	MAIN		
		<u>START'G</u>		
		<u>15</u>		
		<u>17</u>		

R ^{SH} *	Y ^{SH}	BR ^{SH} .
<u>24</u>	<u>25</u>	<u>29</u>
DOWN	DOWN	BARRIERS
MAIN	MAIN	LOCKED
HOME	<u>DISTANT</u>	<u>DOWN</u>
	<u>24</u>	UNLOCKED
	<u>23</u>	

* = BRASS LEVER LEADS

SPARE LEVERS :- 1. 3. 5. 6. 8. 9. 10. 11. 12. 13.

SPACES :- 26. 27. 28
20. 21. 22.