

SERIAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
	8.4.02		LOCKING ALTERED TO CONFORM TO STANDARD PRACTISE. DISTANTS RELEASED BY STARTING SIGNALS IN ADDITION TO HOMES.	
			LINE SINGLED TO LEDBURY BRANCH BOX. E.T. STAFF WORKING	4.1.1917
			LEVER 5 SPARE (BEUEVED WAS TRAP POINT IN SIDING (FORMER UP LINE))	
			CLOSURE OF LEDBURY BRANCH BOX - E.T.S. TO LEDBURY	1925
			SWITCH LEVER PROVIDED	6.9.1930
			BOX REDUCED TO G.F. LINE CLOSED TO LEDBURY	13.7.1959

DYMOCK

S 2669 / 1