

1
DOWN
MAIN
DISTANT
3
2

2
DOWN
MAIN
HOME

3
DOWN
MAIN
START'G
LINE
CLEAR

6
DOWN
MAIN
DETONATORS
OFF
ON

7
BACKING
DOWN
UP
MAIN
14
17
13
OR
14
13
OR
23
22
OR
9
8

8
DISC
FOR
No. 9
9

9
UP
MAIN
UP
SIDING

10
DISC
FOR
No. 9
9

11
DISC
FOR
No. 12
14
17
12
OR
14
12

12
UP
SIDING
TO
CROSS
14

13
DISC
FOR
No. 14
14
17
OR
14

14
MAIN
TO
CROSS

15
DISC
FOR
No. 14
14
12
OR
14

16
DISC
AT
No. 20
14
12
15
OR
14
15

17
No. 1
DOWN
SIDING
TO
CROSS
14

18
DISC
FOR
No. 17
14
12
17
OR
14
17

19
DISC
FOR
No. 20
20

20
DOWN
MAIN
No. 1
SIDING

21
DISC
FOR
No. 20
20

22
DISC
FOR
No. 23
23

23
UP
MAIN
UP
GOODS
LOOP

24
UP
MAIN
FACING
UP
GOODS
LOOP

25
UP
GOODS
LOOP
TO UP
MAIN
STARTING
23

26
UP
MAIN
TO UP
GOODS
LOOP
HOME
23
24
OR
24

27
UP
MAIN
START'G
LINE
CLEAR

28
UP
MAIN
INNER
HOME

29
UP
MAIN
HOME

30
UP
MAIN
DISTANT
[ELECTRIC
SWITCH]
27
28
29

UP
MAIN
DETONATORS
OFF
ON

INSP. STROUD, SWINDON
85/88/2

* IVORINES - REMANDER BRASS

Nos 26.27 & 1JP. DET RE-ORDERED
(NO OBVIOUS REASON)

30.5.1950
INSP. PESTRIDGE
REQ. No. 714

No.25 RE-ORDERED (URGENT) 28.4.1952

MR STARK
REQ. No. 402

1
DOWN
MAIN
DISTANT
2
3

7
DISC
AT 9B
14
17
13
OR
14
13
OR
23
22
13

8
DISC
FOR
9B
9

13
DISC
BACKING
UP
MAIN
TO DOWN
SIDINGS
OR DOWN
MAN OR
UP
GOODS
LOOP
14 OR
17 23
OR 22
14

30
UP
MAIN
DISTANT
29
28
27

IVORINES & CASTINGS
21/2116 2.1.1963
MR. GAINY, FROME

3
DOWN
MAIN
STARTING

22
DISC
FOR
23
23

IVORINES & CASTINGS
27/65
MR. GAINY
13.5.1963