

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			UP MAIN STARTING RENEWED	
			DOWN GOODS LOOP PROVIDED	13.7. 41.
			UP HOME SIGNAL RECOVERED. LEVER A MADE SPARE	by 11. 41
			UP SIDING CONNECTION MOVED NEARER SB	1.6. 54.
B			NEW LOCKING FRAME	15.4. 56
			DOWN MAIN STARTING RENEWED	
			UP MAIN HOME RENEWED AS STRAIGHT POST	
A	1.62		THERMAL TIMER RELAY PROVIDED	
			SPUR OFF DOWN LOOP RECOVERED	13.4. 62.
D			UP SIDING RECOVERED	29.6. 64
F			XOVER RECOVERED	7. 3.65
E	8.64		DOWN DISTANT RENEWED AS CLIGHT 218' FURTHER OUT	65
G	4.65		UP DISTANT RENEWED AS CLIGHT ON SAME SITE	66

C = Plots removed

ATC 11/37

## BROMFIELD

RECORD OF AMENDMENTS

S 2973 / 1/3

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
I			CLOSURE OF LUDLOW S.B.	5.6.68
K	2.75		AWS 1/40 ATC	
J		SP 74/102	BARRIERS 1/40 GATES. Treadle added. UMN moved out?	18.11.75.
M			BLOCK SWITCH RECOVERED	22.10.76 or 77
N	8.79		BOX REWIRED. AAT added One full B + One Acceptance block	
		SP 83/15	SINGLING TO CRAVEN ARMS. PROVISION OF MINI PANEL.	N.C.O.
L	5.76 <del>8.79</del>		CLAMP LIKS ON 19	
		SP 90/2	RECOVERY OF DOWN GOODS LOOP	N.C.O.
			DOWN GOODS LOOP CLIPPED OUT OF USE	
H	3.65		BN PROVIDED! <del>DANN</del> Down Line Home bkl RIN	1965
O	11.83		Cables 1/40 Alters	
P	12.54		HABD	
Q	4.91		Ludlow Arrow xng out.	

BROMFIELD

RECORD OF AMENDMENTS

S 2973 / 1/4