

Accession Numbe	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605336	BR(LM)	CL16/83	11/02/1983		MECH	Macclesfield - dog chart and locking table	Plan also numbered OC3215L
SRS200605337	BR(LM)			30/11/1986	SBD	Madeley	
SRS200605338	BR(LM)	NS865027/1	01/07/1986		SCHEME	Madeley - redundant assets	
SRS200605339	BR(LM)			02/06/1987	SK	Madeley	Amendment B
SRS200605340	BR(LM)	CR-130-82	??/07/1982	07/09/1982	SCHEME	Madeley - proposed P&C layout	Amendment A
SRS200605341	BR(LM)	NS915001/3	31/01/1991		SCHEME	Madeley to Holditch - abolition of Holditch Colliery	
SRS200605342	BR(LM)	NS915001/1	31/01/1991		SCHEME	Madeley to Holditch - abolition of Holditch Colliery	
SRS200605343	BR(LM)	Z1054			SBD	Meaford Crossing - illuminated panel diagram	Stamped 07/01/1993
SRS200605344	BR(LM)		10/09/1990		MISC	Meaford Crossing - sighting report signals MD106R, MD106, MD104, MD23R, MD103, MD105	
SRS200605345	BR(LM)	3243L	04/09/1979		MECH	Meaford Crossing - locking table and name and pull plates	
SRS200605346	BR(LM)	CS156/74/1	02/08/1974		SCHEME	Meaford Crossing - provision of manned lifting barriers	
SRS200605347	BR(LM)	CS107/79/1	01/06/1979		SCHEME	Meaford Crossing - provision of CCTV monitored barriers at Church Lane Crossing	
SRS200605348	BR(LM)				MECH	Milnthorpe No.2 GF - dog chart and locking table	Two copies.
SRS200605349	Railtrack	95-BS-600/12	19/06/1995		SCHEME	Mold Jcn - Sandycroft - recovery of up goods line (minimum work)	Version B. Sheet 1 of 2.
SRS200605350	Railtrack	95-BS-600/12	20/06/1995		SCHEME	Mold Jcn - Sandycroft - recovery of up goods line (minimum work)	Version A. Sheet 2 of 2.
SRS200605351	BR(LM)				ARCH	Mow Cop - relay room internal layout	
SRS200605352	BR(LM)				SBD	Mow Cop - relay room internal layout	Stamped 21/05/1986 Office Copy
SRS200605353	BR(LM)				MECH	Neasden Jcn - lever frame details (locking table)	Stamped 18/07/1984 Office Copy
SRS200605354	BR(LM)				SBD	Neasden Jcn	
SRS200605355	BR(LM)	NL/273/77/1	17/12/1977		MECH	Neasden Midland - dog chart	annotated "amended 16/12/1977 after site visit". Neasden Midland is Neasden Jcn.
SRS200605356	BR(LM)	NL/273/77/1	17/12/1977		MECH	Neasden Midland - dog chart	Second copy of SRS200605355
SRS200605357	BR(LM)				SBD	Neasden Jcn	with amendments written on
SRS200605358	BR(LM)				SBD	Neasden Jcn - copy of part of SB diagram	annotated "check positioning of 9/12 (signals)"
SRS200605359	BR(LM)	93-WS-008/3	26/11/1993		SCHEME	Neasden Jcn SB - recovery of Taylor's Lane Willesden Powergen Sidings	
SRS200605360	BR(LM)				MISC	Brent Jcn and Cricklewood to Acton Wells Jcn - gradient diagram	
SRS200605361	BR(LM)		30/08/1990		MISC	Neasden - closure of SB	written note of details of work to be carried out
SRS200605362	BR(LM)				MISC	Neasden - Acton Wells Jcn and Old Oak Sidings - South Acton Jcn - gradient diagram	

Accession Number	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605363	BR(LM)		03/11/1990		MISC	Neasden Jcn SB - new SB Diagram	Letter from STS Section Birmingham to Dave Collins, Works Engineer Bletchley SWE Depot
SRS200605364	BR(LM)		06/09/1990		MISC	Neasden Jcn SB - proposed arrangement for positioning of new illuminated diagram	
SRS200605365	BR(LM)	SP89/9C	14/03/1990		MISC	Neasden Jcn SB - proposed position of new illuminated diagram	drawing of block shelf with new diagram position
SRS200605366	BR(LM)		24/08/19??		MISC	Neasden Jcn SB - possible collapse	letter on this subject and also proposed work at Saltley Depot
SRS200605367	BR(LM)	SP89/9/3	26/01/1998		SCHEME	Neasden Jcn - alterations icw Marylebone Scheme	Amendment B. Stamped 14/08/1990.
SRS200605368	BR(LM)	MR16/87	19/06/1987		SCALE	Newton-le-Willows Jcn - 1988 relay programme job no. 33887	
SRS200605369	BR(LM)	MR-156-85			SCALE	Newton-le-Willows - proposed relaying of lead to Motorail Terminal	Stamped 26/11/1986
SRS200605370	Westinghouse	RP.1364A	30/01/1961		SBD	Norton Bridge Jcn - layout of front panel for control desk	
SRS200605371	BR(LM)				SBD	Norton Bridge Jcn - L/H panel	Stamped 28/06/1993
SRS200605372	BR(LM)				SBD	Norton Bridge Jcn - R/H panel	Stamped 28/06/1993
SRS200605373	BR(LM)				SBD	Norton Bridge Jcn - Middle panel	Stamped 28/06/1993
SRS200605374	BR(LM)	CR-3-90	14/01/1990		SCALE	Norton Bridge - relaying 1990 item no. 7080250 layout D and E	includes track circuit details
SRS200605375	BR(LM)	CR-93-86	??/11/1987	18/11/1987	SCALE	Norton Bridge - relaying items 7033548 and 7033558	Amendment A. Includes track circuit details.
SRS200605376	BR(LM)	NS855026/1	16/07/1985		SCHEME	Norton Bridge (Great Bridgeford) - redundant assets	
SRS200605377	BR(LM)	NS875062/3	27/11/1987		SCHEME	Norton Bridge Jcn - ACE 1988 relaying items 7033548 and 7033558	
SRS200605378	BR(LM)	CR-5-90	14/01/1990		SCALE	Norton Bridge - relaying 1990 item no. 7080250 layout A	includes track circuit details
SRS200605379	BR(LM)	CR-93-86	??/11/1986		SCALE	Norton Bridge - relaying items 7033548 and 7033558	Includes track circuit details. Annotated 'preliminary'
SRS200605380	BR(LM)	CS29/80/1	07/03/1980		SCHEME	Norton Bridge Jcn - up fast audible warning system	
SRS200605381	BR(LM)	NW841013	16/11/1984		SCHEME	Norton Bridge Jcn - 1985 relaying and recovery of down loop	marked 'draft'
SRS200605382	BR(LM)	NS875062	27/11/1987		SCALE	Norton Bridge Jcn - ACE 1988 relaying items 7033548 and 7033558	
SRS200605383	Westinghouse	RP.1364A			SBD	Norton Bridge Jcn - layout of front panel for control desk	Version AC1. Stamped 06/01/1995.
SRS200605384	BR(LM)	NW900061/8			SCHEME	Norton Bridge Jcn - line speed improvement	Issued 29/08/1990. Supersedes W890139.
SRS200605385	BR(LM)	616-90		23/08/1990	MISC	Norton Bridge - new gantry for signals 154 and 153 gravity bases	Drawing of equipment. Amendment A.

Accession Number	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605386	BR(LM)	924-89	13/10/1989	23/08/1990	MISC	Norton Bridge - new gantry for signals 154 and 153 general arrangement	Drawing of equipment. Amendment C.
SRS200605387	BR(LM)	CR-5-90	14/01/1990		SCALE	Norton Bridge - relaying 1990 item no. 7080250 layout A	
SRS200605388	BR(LM)	CR-4-90	12/01/1990		SCALE	Norton Bridge - relaying 1990 item no. 7080250 layouts B and C	Includes track circuit details
SRS200605389	BR(LM)	CR-44-85	??/03/1985		SCALE	Norton Bridge - relaying item 175127	
SRS200605390	BR(LM)	NW851023/3A	14/10/1985		SCHEME	Norton Bridge Jcn - provision of flashing yellow signal aspects on down fast line	
SRS200605391	BR(LM)	CS38/73/7A			SCHEME	Nuneaton - remodelling for high speed running	Issued 18/02/1973. Document in poor condition.
SRS200605392	BR(LM)	NW870084C/3	01/11/1990		SCHEME	Nuneaton PSB - abolition of Abbey Jcn and Midland Jcn SBs and additional signalling facilities	
SRS200605393	BR(LM)	NW870084	05/12/1990		SCHEME	Nuneaton PSB (Stage 2A) - commissioning of new colour light and track circuits at Hinckley	
SRS200605394	BR(LM)	NW861006/3	19/06/1986		SCHEME	Nuneaton - provision of flashing yellow aspects for signal NN82	
SRS200605395	BR(LM)	NW870084C/3	12/12/1989		SCHEME	Nuneaton PSB - abolition of Abbey Jcn and Midland Jcn SBs and additional signalling facilities	Extract amended to show repositioning of 9 and 7/9 AWS magnets. With attached letter from Director S&TE Birmingham dated 22/12/1989.
SRS200605396	BR(LM)		16/10/1992		MISC	Nuneaton PSB - proposed higher speed turnout to down slow at Attleborough. P	Project specification and cost estimate. With attached routing slip.
SRS200605397	BR(LM)		16/10/1992		MISC	Nuneaton PSB - proposed higher speed turnout to down slow at Attleborough. P	Second copy of SRS200605396
SRS200605398	BR(LM)	NW872041/3	13/04/1987		SCHEME	Oubeck Interlocking (Preston PSB) - relaying and conversion of Bay Horse Emergency Crossovers to Push Button operation	
SRS200605399	BR(LM)				MECH	Bay Horse North GF - dog chart and locking table	
SRS200605400	BR(LM)				MECH	Bay Horse South GF - dog chart and locking table	
SRS200605401	Westinghouse	PMP000	??/06/1972		SBD	Oubeck - general arrangement of monitoring panel	
SRS200605402	BR(LM)				SBD	Oxenholme Emergency Frame	
SRS200605403	RSM Controls	1142/1A	15/08/1972		SBD	Oxenholme - general arrangement of monitoring panel	
SRS200605404	BR(LM)	CL103/71	26/04/1971		MECH	Parkside Frame - dog chart and locking table	Includes lever colour and nameplate tables.
SRS200605405	Westinghouse	WMP0003	??/01/1972		SBD	Parkside - general arrangement of monitoring panel	Sheet 1 of 2
SRS200605406	Westinghouse	WMP0003	??/01/1972		SBD	Parkside - general arrangement of monitoring panel	Sheet 2 of 2

Accession Number	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605407	BR(LM)	MS917319	28/03/1991		MISC	Penrith - permission to cross indicator	drawing of construction details
SRS200605408	BR(LM)	NW710068			MECH	Penrith GF - lever signal and block controls	Locking table. Sheet 2. Stamped 23/06/1971.
SRS200605409	BR(LM)				SBD	Penrith GF	Stamped 25/10/1993. Office copy.
SRS200605410	BR(LM)				SBD	Plumpton No.2 Emergency Frame	Stamped 03/02/1994. Office copy.
SRS200605411	BR(LM)	NW872042/3	14/04/1987		SCHEME	Plumpton Interlocking - relaying and conversion of Southwaite No.1 and No.2 emergency crossovers to push button operation.	
SRS200605412	BR(LM)				SBD	Southwaite No.2 Emergency Frame	
SRS200605413	BR(LM)				SBD	Southwaite No.1 Emergency Frame	
SRS200605414	BR(LM)				MECH	Southwaite No.1 GF - dog chart and locking table	
SRS200605415	Railtrack		29/04/1999		SBD	Prees	Version AC2. With attached miscellaneous paperwork related to installation.
SRS200605416	BR(LM)	NW872005/3	16/01/1987		SCHEME	Preston PSB - abolition of Ribble Yard GF and remodel of Skew Bridge Jcn	
SRS200605417	BR(LM)	93-BS-624/20	27/10/1993		SCHEME	Preston PSB - provision of treadles for Brock r/g lights	
SRS200605418	BR(LM)	D910018/3	01/07/1991		SCHEME	Preston PSB - White Horse Tunnel. Provision of fixed audible staff warning system.	Marked "draft copy"
SRS200605419	BR(LM)	D910018/3	01/07/1991		SCHEME	Preston PSB - White Horse Tunnel. Provision of fixed audible staff warning system.	Revision A. Stamped "issued 10/06/1993"
SRS200605420	BR(LM)			25/10/1972	MECH	Ribble Yard GF - name and pull plate lists	
SRS200605421	BR(LM)	W69A	21/11/1952	25/10/1972	MECH	Ribble Yard GF - dog chart and locking table	
SRS200605422	BR(LM)	MD86536	02/06/1986		SCHEME	Ridgmont - provision of AOCL	Stamped "provisional"
SRS200605423	BR(LM)	MD86536	02/06/1986		SCHEME	Ridgmont - provision of AOCL	Second copy of SRS200605422
SRS200605424	BR(LM)	94-BS-620/20		08/06/1994	SCHEME	Rugby PSB - provision of PLGS for up slow and up fast LOS	Amendment A
SRS200605425	BR(LM)	W890080/3	15/05/1989		SCHEME	Rugby PSB - extract for DVT working	
SRS200605426	BR(LM)	W4/44278	??/08/1988		MISC	Rugby - modification of train describer system to incorporate Northampton Control Area	Project specification
SRS200605427	BR(LM)	D910046/3	29/11/1991		SCHEME	Rugby - provision of down Brinklow loop	
SRS200605428	BR(LM)		12/11/1992		MISC	Rugby PSB - proposed flashing aspects icw signal 332 (Brinklow)	Project specification and cost estimate. With attached routing slip.
SRS200605429	BR(LM)	W880078/18	04/05/1988		SCHEME	Rugby PSB - provision of flashing aspects on up and down slow lines at Hanslope	
SRS200605430	BR(LM)	DS945016	09/12/1994		SCHEME	Rugby PSB - recovery of No.4 Siding at Rugby North (minimum work)	Version A
SRS200605431	BR(LM)	94-BS-620/20	22/04/1994		SCHEME	Rugby PSB - provision of PLGS for up slow and up fast LOS	annotated "superseded by Amendment A"
SRS200605432	BR(LM)	W880078/3	04/05/1988		SCHEME	Rugby PSB - provision of flashing aspects on up and down slow lines at Hanslope	
SRS200605433	BR(LM)	W900013/3	??/02/1990		SCHEME	Rugby PSB - line speed improvements, DVT working and Weedon TOWS	

Accession Number	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605434	BR(LM)	94-WS-013/3	21/07/1994		SCHEME	Rugby - movement of warning indicator board for down Brinklow loop	Version A
SRS200605435	BR(LM)	93-WS-006/3	20/05/1993		SCHEME	Rugby - provision of Brinklow flashing aspects	
SRS200605436	BR(LM)	D910046/3	04/02/1993		SCHEME	Rugby - provision of down Brinklow loop	Amendment A
SRS200605437	BR(LM)	93-WS-006/3A	20/05/1993		SCHEME	Rugby - provision of Brinklow flashing aspects	
SRS200605438	BR(LM)	93-WS-006/3A		08/03/1994	SCHEME	Rugby - provision of Brinklow flashing aspects	Version A
SRS200605439	BR(LM)	NS/277/74	22/09/1974		SCHEME	Rugby PSB - remodelling up side north	
SRS200605440	BR(LM)	NW860111	03/10/1986		SCHEME	Rugby PSB - provision of patrolman's lockout on up fast line to Nuneaton	
SRS200605441	BR(LM)	W880169/3	29/08/1990		SCHEME	Rugby PSB - proposed new station at Roade	
SRS200605442	BR(LM)	NW860041/3	25/04/1986		SCHEME	Rugby PSB - abolition of Welton GF No.1	
SRS200605443	BR(LM)	W882035/3	13/09/1988		SCHEME	Rugby PSB - Kilsby Tunnel. Provision of additional signals.	
SRS200605444	BR(LM)	NW860086	??/05/1986	01/06/1989	SBD	Rugby PSB - miniature console layout	Version AH1
SRS200605445	BR(LM)	Notice to Traffic 3080			MISC	Rugby - station area alterations 28/02/1980 to 02/03/1980	
SRS200605446	BR(LM)	Notice to Traffic	30/10/1978		MISC	Long Buckby - provision of hot box detector on up main 14/11/1978	Marked "this notice is cancelled"
SRS200605447	BR(LM)	Notice to Traffic	23/10/1979		MISC	Rugby PSB - new crossover 455A/B into use 18/11/1979	
SRS200605448	BR(LM)	Notice to Traffic	02/02/1972		MISC	Rugby PSB - audible warning device into use south end 20/02/1972	
SRS200605449	BR(LM)	Notice to Traffic	16/06/1981		MISC	Rugby station - points 457B converted to clamp lock operation 12/07/1981	
SRS200605450	BR(LM)	Notice to Traffic	16/05/1983		MISC	Kilsby and Crick GF - conversion to push button operation 10/07/1983	
SRS200605451	BR(LM)	Notice to Traffic	14/09/1981		MISC	Rugby station - up goods to up fast line connection and associated slip (489) out of use 04/10/1981	
SRS200605452	BR(LM)	Notice to Traffic	14/09/1981		MISC	Rugby station - up and down engine line to up goods connection (490) out of use 22/11/1981	
SRS200605453	BR(LM)	Notice to Traffic	29/01/1975		MISC	Hanslope Junction area- Yodalarm warning system installed 05/03/1975	
SRS200605454	BR(LM)	Notice to Traffic	07/11/1980		MISC	Rugby - up main to up Northampton facing crossover (455) recovered and new longer crossover laid in 07/12/1980	
SRS200605455	BR(LM)	Notice to Traffic	17/02/1978		MISC	Rugby (flyover area) - position light ground signal RY166 abolished 12/03/1978	
SRS200605456	BR(LM)	Notice to Traffic	07/11/1980		MISC	Rugby - up main to up Northampton facing crossover brought into use 14/12/1980	
SRS200605457	BR(LM)		26/09/1979		MISC	Rugby - notice to traffic 1622 issued 19/02/1979 and subsequently cancelled will be reinstated for 28/10/1979	Notice to Traffic (unnumbered)

Accession Number	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605458	BR(LM)	Notice to Traffic	08/11/1978		MISC	Althorp Park - hot box detector provided on up main 14/11/1978	
SRS200605459	BR(LM)	Notice to Traffic	06/01/1981		MISC	Hillmorton - various connections and signals taken out of use 15/02/1981	
SRS200605460	BR(LM)	Notice to Traffic	23/10/1979		MISC	Rugby PSB - facing crossover 455A/B to be relayed 04/11/1979	
SRS200605461	BR(LM)	Notice to Traffic	29/05/1981		MISC	Blisworth - signal RY19 to be renewed 05/07/1981	
SRS200605462	BR(LM)	Notice to Traffic	13/03/1981		MISC	Rugby station - up fast to up slow facing crossover (459) out of use. Associated track and signal alterations. 19/04/1981	
SRS200605463	BR(LM)	Notice to Traffic	27/07/1972		MISC	Rugby PSB area - permanent speed restriction boards into use at various locations 23/08/1972	
SRS200605464	BR(LM)	Notice to Traffic	16/10/1981		MISC	Rugby station - work shown on Notice to Traffic 3532 now to be carried out 08/11/1981	
SRS200605465	BR(LM)	Notice to Traffic	26/11/1981		MISC	Linslade Tunnel - audible warning system installed 03/01/1982	
SRS200605466	BR(LM)	Notice to Traffic	19/07/1973		MISC	Brandon Ballast Pit - existing crossover to be disconnected 22/07/1973 and new crossover and GF commissioned 19/08/1973	Amendment to Notice to Traffic 6726
SRS200605467	BR(LM)	Notice to Traffic	14/09/1981		MISC	Rugby station - new up goods to up fast connection (459) into use 25/10/1981	
SRS200605468	BR(LM)	Notice to Traffic	12/01/1973		MISC	Brandon Ballast Pit - existing trailing crossover disconnected and new crossover and GF commissioned 20-27/05/1973	
SRS200605469	BR(LM)	Notice to Traffic	11/11/1980		MISC	Hanslope Junction - flashing yellow aspects on signals RY201,RY177,RY215 07/12/1980	
SRS200605470	BR(LM)		26/09/1979		MISC	Rugby - Notice to Traffic 1527 subsequently cancelled now reinstated for 14/10/1979	Notice to Traffic (unnumbered)
SRS200605471	BR(LM)	Notice to Traffic	22/07/1982		MISC	Weedon - audible warning system to be provided 05/09/1982	
SRS200605472	BR(LM)	Notice to Traffic	12/01/1979		MISC	Rugby - relaying of 455A/B facing crossover 18/02/1979	
SRS200605473	BR(LM)	Notice to Traffic	04/06/1975		MISC	Rugby PSB - signals RY337 and RY338 operational 20/07/1975	
SRS200605474	BR(LM)	Notice to Traffic	30/10/1978		MISC	Long Buckby - provision of hot box detector on up main 14/11/1978	
SRS200605475	BR(LM)	Notice to Traffic	12/01/1979		MISC	Rugby - relaying of 455A/B facing crossover 25/02/1979	Amended from 18/02/1979
SRS200605476	BR(LM)	Notice to Traffic	17/06/1982		MISC	Welton GF - ground frame controlling crossover has been taken out of use	
SRS200605477	BR(LM)	Notice to Traffic	29/05/1981		MISC	Heyford - signals applying into up loop and down loop have been temporarily taken out of use	

Accession Number	Company	Reference	Date created	Last modified	Type	Description	Comments
SRS200605478	BR(LM)	Notice to Traffic	19/02/1979		MISC	Rugby PSB - up Northampton goods line south of bridge no.275 recovered 18/03/1979	All text crossed through [cancelled?]
SRS200605479	BR(LM)	Notice to Traffic	08/11/1973		MISC	Bilton Sidings - crossbar shunting signal to be provided 20/12/1973	
SRS200605480	BR(LM)	Notice to Traffic	22/05/1975		MISC	Rugby PSB - repositioning of position light ground signal RY171 and associated notice board 18/06/1975	
SRS200605481	BR(LM)	Notice to Traffic	01/07/1975		MISC	Rugby PSB - signals RY337 and RY338 taken out of use until further notice	
SRS200605482	BR(LM)	Notice to Traffic	07/01/1982		MISC	Stowe Hill Tunnel - tunnel warning system installed 07/02/1982	
SRS200605483	BR(LM)	Notice to Traffic	22/10/1972		MISC	Brinklow - trailing crossover and GF out of use 05/11/1972	
SRS200605484	BR(LM)	Notice to Traffic	01/03/1978		MISC	Rugby station area - AWS test inductor has been repositioned to 100m approach side of signal RY77	
SRS200605485	BR(LM)	Notice to Traffic	22/07/1982		MISC	Bilton Sidings - new signs to be erected 19/09/1982	
SRS200605486	BR(LM)		??/08/1986		MECH	Rugeley No.1 and No.2 GFs - dog chart and locking table	
SRS200605487	BR(LM)				SBD	Rugeley No.1 GF	