

SER -IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			LAYOUT ALTERED & G.F. RECOVERED	1911
			WEST BAY S.B. REDUCED TO G.F.	18.1. 1927
			EAST STREET XING G.F. RECOVERED	c. 1930
			UP STARTINGS BRACKET RENEWED ADJACENT TO MAIN LINE	22.8. 1938
	7.48		BRADPOLE XING G.F. RENEWED (CLASS 5, 3 LEVERS)	
			UP ADVANCED STARTING & LOWER DISTANT RENEWED AS U.Q.	c. 1. 1953
			SIGNAL 27 RENEWED AS ELEVATED DISC	19.7. 1953
			SIGNALS 14/25 RENEWED @ 16x	6. 11. 1959

BRIDPORT

RECORD OF AMENDMENTS

S

/1