

5
DOWN
MAIN
ADVANCED
STARTING
LINE
CLEAR

31
UP
MAN
STARTING
LINE
CLEAR

IVORINES & CASTINGS
1.11.1946

26
UP
MAIN
FROM
UP
AVOIDING
LINE

33
UP
MAIN
INNER
DISTANT
31
32

IVORINES & CASTINGS
INSP. TABER, FROME
UNDATED

REASON?

33
UP
MAIN
DISTANTS
31
32

IVORINE ONLY
INSP. TABER
30.3.1950

FRESHFORD

S 430/7