

Accession Number	Company	RailRef	Digitised	Reference	Date created	Last modified	Type	Description	Comments
SRS201600711	BR(S)	LB070-310			??/??/????		NUMB	Brighton South	Manuscript diagram by P Hawes
SRS201600712	BR(S)	LB090-005			??/??/????		NUMB	Brighton West	Manuscript diagram by P Hawes
SRS201600713	BR(S)	SE004-030			27/12/1957		NUMB	Cannon Street	Article and diagram from <i>Railway Gazette</i>
SRS201600714	BR(S)	SE060-070			??/??/????		MISC	Canterbury West - barrier controls	Photocopies
SRS201600715	BR(S)	SE001-340			12/06/1959		NUMB	Chislehurst Junction	Diagram from <i>Railway Gazette</i>
SRS201600716	BR(S)	SE020-270		RS.11/CP	09/10/1970		MISC	Dartford - arrangements for resignalling on 31/10/1970	
SRS201600717	BR(S)	SW083-005			??/??/????		NUMB	Fratton - Portsmouth GF 'A'	Photocopy of manuscript diagram and notes
SRS201600718	BR(S)	SE120-210		No 1926A	03/02/1976	11/02/1991	MECH	Gillingham - locking tables	Sheets 1 and 2
SRS201600719	BR(S)	SE001-260		No 1921	02/05/1964	10/03/1971	SK	Hither Green	
SRS201600720	BR(S)	SE001-260		No 1921	02/05/1964	22/03/1971	SK	Hither Green	
SRS201600721	BR(S)	SE001-260			02/04/1971		MISC	Hither Green - track circuit failures	Typescript report
SRS201600722	BR(S)	LB004-020		LE10437	27/08/1951	13/09/1951	ARCH	Leigham Junction - reconstruction of box	
SRS201600723	BR(S)	SE041-110			??/??/????		SBD	Robertsbridge	
SRS201600724	Godwin Warren	SW012-016		11101	25/07/1963		CIRC	West Barnes Crossing - barrier control circuits	
SRS201600725	LSW			R.2	13/07/1891	13/05/1892	MISC	Requirements for continuous brakes on mixed trains	File of correspondence etc
SRS201600726	BR(S)			C/2641/3	10/10/1967		MISC	BR standard tubular signals	Signalling Instruction No 112
SRS201600727	BR(S)			M70-2	27/10/1967		MISC	Standard signal profiles	
SRS201600728	BR(S)			C/29761	26/02/1969		MISC	Tubular posts for colour light signals	General Instruction No 112
SRS201600729	BR(S)			C/46717	10/10/1969		MISC	Testing impedance bond connections	Signalling Instruction No 131
SRS201600730	BR(S)			M21-9	05/05/1971		MISC	Clamp lock and detection mechanism	
SRS201600731	BR(S)			A/22222	02/05/1973	29/11/1973	MISC	Provision of banner repeaters	Signalling Instruction No 159
SRS201600732	BR(S)			C/46663	15/04/1975		MISC	Signalling into terminal platform lines	Signalling Instruction No 171
SRS201600733	BR(S)			D/21/90-2	20/06/1977		MISC	BR standard colour light signals	
SRS201600734	BR			4/228-10-5	??/09/1977		MISC	Schedule of telecommunications cables	
SRS201600735	BR(S)				13/03/1970		SCHEME	Lewisham - Woolwich / Welling	Annotated with duties of gangs
SRS201600736	BR(S)			234Z	04/09/1978	17/12/1979	SCHEME	Richmond - Gunnersbury	
SRS201700157	BR(S)	LB080-280		R/2435/1	20/07/1992		MISC	Arundel - special instructions	
SRS201700158		LB001-130			??/??/????		NUMB	Balham Intermediate	Manuscript diagram
SRS201700159	BR(S)	LB090-260		LSIBIBH/1	??/01/1992		MISC	Barnham - special instructions	
SRS201700160	BR(S)	LB090-350		No 1133B-1	23/08/1974		ELEC	Bosham - electrical locking table	
SRS201700161	BR(S)	LB040-060		No 1035	30/08/1974		SK	Bricklayers Arms Junction	
SRS201700162	BR(S)	LB070-310		No 1177	15/02/1974		SK	Brighton	
SRS201700163	BR(S)	LB090-350		LCKBL/1	??/09/1989		MISC	Brook Lane LC [Bosham] - special instructions	
SRS201700164	BR(S)	LB090-330		LSBICC/1	??/12/1991		MISC	Chichester - special instructions	
SRS201700165	BR(S)	LB090-330		LSBICC/1	23/10/1992		MISC	Chichester - special instructions	
SRS201700166	BR(S)	LB090-330		C698-OPIN26	??/10/1992		MISC	Chichester - LC operator's guide	
SRS201700167		LB001-080			??/??/????		NUMB	Clapham Junction 'B'	Manuscript diagram
SRS201700168	BR(S)	SE120-500			01/08/1991	31/08/1991	MISC	Dover Marine - particulars of working traffic	Daily sheets
SRS201700169	BR(S)	SW001-160			07/04/1989		MISC	Durnsford Road - report on accident 06/04/1989	
SRS201700170	BR(S)	SW070-190		No 88	23/06/1974		SK	Eastleigh	

Accession Number	Company	RailRef	Digitised	Reference	Date created	Last modified	Type	Description	Comments
SRS201700171	BR(S)	LB090-340		No 1188A	21/09/1990		MECH ELEC	Fishbourne Crossing - mechanical and electrical locking tables	
SRS201700172	BR(S)	LB090-340		LSBIFC/1	??/11/1991		MISC	Fishbourne Crossing - special instructions	
SRS201700173	BR(S)	LB090-340		LSBIFC/1	04/04/1992		MISC	Fishbourne Crossing - special instructions	
SRS201700174	BR(S)	LB090-350		No 52L 1988	??/06/1988		MISC	Funtington LC [Bosham] - instructions	
SRS201700175		LB001-200			??/??/????		NUMB	Gloucester Road Junction	Manuscript diagram
SRS201700176	BR(S)	LB095		BR29628/18	??/??/????		MISC	Havant - Hayling Island - train staff ticket	Unused
SRS201700177	BR(S)	LB090-360		No 59L 1988	??/06/1988		MISC	Inlands Road LC - instructions	
SRS201700178	BR(S)	LB084-010 63B 1988		LSBICBH/1	??/06/1988		MISC	Leatherhead - special instructions	
SRS201700179	BR(S)	SE020-470			??/04/1979	14/05/1979	SCHEME	Maidstone West - stages 1 - 4 and final	Manuscript diagrams
SRS201700180	BR(S)	LB040-075		No 1054	25/10/1974		SK	New Cross Gate	
SRS201700181	BR(S)	LB040-075		No 1054A/B	23/09/1990		MECH ELEC	New Cross Gate - mechanical and electrical locking tables	
SRS201700182		LB001-100			??/??/????		NUMB	New Wandsworth	Manuscript diagram
SRS201700182A	BR(S)	SE036-010		No 1562	??/??/????		SK	Northfleet APCM Control Room	
SRS201700183		LB040-180			??/??/????		NUMB	Norwood Fork Junction	Manuscript diagram
SRS201700184		LB001-070			??/??/????		NUMB	Pouparts Junction	Manuscript diagram
SRS201700184A	BR(S)	SW100-040		No 237A/B	03/11/1981		MECH ELEC	Redbridge - mechanical and electrical locking tables	
SRS201700185		LB001-190			??/??/????		NUMB	Selhurst	Manuscript diagram
SRS201700186	BR(S)	SW100-010			28/03/1984		MISC	Southampton Tunnel - sighting meeting	
SRS201700187	BR(S)	LB090-370		No 275L 1988	??/12/1988		MISC	Southbourne - instructions	
SRS201700188		LB020-100			??/??/????		NUMB	Streatham	Manuscript diagram
SRS201700189		LB001/150			??/??/????		NUMB	Streatham Common	Manuscript diagram
SRS201700190		LB001-140			??/??/????		NUMB	Streatham North Junction	Manuscript diagram
SRS201700191		LB020-110			??/??/????		NUMB	Streatham South Junction	Manuscript diagram
SRS201700192		SW140-126			15/07/1995		NUMB	Templecombe 'A'	Manuscript diagram
SRS201700192A	BR(S)	LB001-023		No 1063	11/02/1974		SK	Victoria Central	
SRS201700193	BR(S)	SE101-010		No 1522	13/11/1977		SK	Victoria Eastern	
SRS201700194	BR(S)	LB001-023		No 1063Z	12/01/1977	02/11/1979	SCHEME	Victoria - Battersea Park Junction - stageworks	
SRS201700195	BR(S)	SW001-170		No 324	23/09/1960		SK	Wimbledon 'A'	
SRS201700196	BR(S)	SW001-170		No 324A/B	23/09/1960		MECH ELEC	Wimbledon 'A' - mechanical and electrical locking tables	
SRS201700197	BR(S)	SW001-170		No 324A-1	21/03/1983		MECH	Wimbledon 'A' - mechanical locking table	
SRS201700198	BR(S)	SW001-170		No 324A-2	21/03/1983		MECH	Wimbledon 'A' - mechanical locking table	
SRS201700199		LB040-190			??/??/????		NUMB	Windmill Bridge Junction	Manuscript diagram
SRS201700200	Elliott	SW001			??/??/????		MISC	West Byfleet - St Denys - train describer operating instructions	
SRS201700201	BR(S)				??/??/????		MISC	Control panels - method of operation	
SRS201800089	BR(S)	LB070-210	Yes	No 1119	25/06/1983		SBD	Burgess Hill GF	
SRS201800090	BR(S)	SW104-010	Yes	No 580	02/12/1971		SBD	Marchwood	
SRS201800091	BR(W)	SW250-020	Yes	S435/12	10/04/1958		SBD	Midford	
SRS201800092	BR(S)	SE020		RS11/CP	14/03/1970		MISC	North Kent resignalling - arrangements for Stage 1	
SRS201800093	WB&S			E7602	11/07/1958		MISC	Electrically operated switch diamond crossing	
SRS201800094	WB&S			E8018	17/07/1959		MISC	Electrically operated switch diamond crossing	

Accession Number	Company	RailRef	Digitised	Reference	Date created	Last modified	Type	Description	Comments
SRS201800095	BOT	SW250		1160	02/03/1886		MISC	Inspection report - Chilcompton - Radstock doubling	Photocopy
SRS201800096	BOT	SW250		2234	14/04/1886		MISC	Inspection report - Chilcompton - Radstock signal alterations	Photocopy
SRS201800097	BOT	SW250		7967	29/08/1892		MISC	Inspection report - Wellow - Midford doubling	Photocopy
SRS201800098	BOT	SW250		7832	29/06/1894		MISC	Inspection report - Radstock - Wellow doubling	Photocopy
SRS201800099	BOT	SW250		10544	21/04/1900		MISC	Inspection report - Midsomer Norton and Evercreech Junction new sidings	Photocopy
SRS201800100		SW250					MISC	Inspection reports - S&DJ	Manuscript notes
SRS201800101		SW250			04/11/1876		MISC	Railway News report on Radstock accident	Photocopy