

SERIAL	DATE	PLAN No.	DETAILS	OCC'N
			ADDITIONAL SIGNALLING PROVIDED (SIGNAL 8, DISCS 9&10?)	
			DISTANTS FIXED AT DANGER	
			YELLOW DISTANT ARMS & LIGHTS	
				4.1928
			E.T. TOKEN TO YATTON WEST	
				c 1929 ?
			FRAME RELOCKED V.T. 5 BAR. LAYOUT AMENDED. UP HOME RENEWED AS L.H. BRACKET. 22T AND 28T PROVIDED. SIGNAL 41 RECOVERED	1949
			SIGNALS 5/7 RENEWED (OR ALTERED)	
	8.51		14 LED BY 13 (33W 15R 16W) LOCKS ON.	
A			S.B. WORKED AS G.F. E.T.T. TO SANDFORD & BANWELL RECOVERED.	
				28.10.1963
			UP MAIN OUT OF USE. + OVER & SLIP. UP SIDINGS SPIKED. UP ADV'CD START'G & DOWN HOME RETAINED - REMAINDER RECOVERED.	1.7.1964

CONGRESBURY

RECORD OF AMENDMENTS

S 428 / 1