

1
DOWN
MAIN
DISTANTS
2

2
DOWN
MAIN
HOME
26

3
DOWN
RELIEF
HOME
TO
DOWN
MAIN
26
24

5*
DOWN
MAIN
DETONATORS
OFF
ON

10
DOWN
SIDINGS
STARTING
TO
SPUR

11
DOWN
SIDINGS
STARTING
TO
DOWN
MAIN
26
13

13
THROUGH
SIDING
SIDINGS
17

14
THROUGH
SIDING
HOME
TO
DOWN
MAIN
26
17

15
THROUGH
SIDING
STARTING

17
DOWN
RELIEF
TO
CROSS
24

18
INTERLOCKING
LEVER
FOR
SILK
MILL
G.F.

19
DISC
DOWN
RELIEF
HOME
TO
UP
SIDING
28
27
26
24
31

24
DOWN
MAIN
DOWN
RELIEF

26
FPL
FOR
27B

27
UP AND
DOWN
MAIN
FACINGS
* OVER

28
UP
MAIN
UP
SIDING

SILK MILL CROSSING

31
FPL
FOR
27A

32
WORKED
TO
MAINTAIN
LOCKING

38
UP
STARTING
FROM
DOWN
RELIEF
TO
THROUGH
SIDING
OR DOWN
SIDINGS
(SELECTED)

40
DISC
FOR
28A
27
28
31
32
38

44
UP
MAIN
DETONATORS
OFF
ON

45
UP
MAIN
HOME
TO
THROUGH
SIDING
OR DOWN
SIDINGS
27
31
38

48
UP
MAIN
HOME
31

49
UP
MAIN
DISTANT
48

50
BARRIERS
LOCKED
DOWN
UNLOCKED

* BRASS

SILK MILL CROSSING	MRLL
	S