

1
DOWN
MAIN
DISTANT
2
3
4

2*
DOWN
MAIN
HOME

3*
DOWN
MAIN
START'G

4
DOWN
MAIN
ADVANCED
STARTING

10
DISC
AT 11B

11
DOWN
MAIN
SPUR

12
DISC
FOR
11A
11

13
DISC
FOR
15B
15

15
MAIN
+ OVER

16
DISC
FOR
15A
15

17
DISC
DOWN
SIDINGS
TO
SPUR

21*
DISC
FOR
NO. 22
22

22
DOWN
MAIN
DOWN
SIDINGS

23
DISC
AT 22C

25
UP
MAIN
ADVANCED
STARTING

26*
UP
MAIN
START'G

27*
UP
MAIN
HOME

28
UP
MAIN
DISTANT
27
26
25

1
DOWN
MAIN
DETONATORS
OFF
ON

2
UP
MAIN
DETONATORS
OFF
ON

* BRASSES

DRUMP LANE	
LEVER LEADS	

DRUMP LANE LEVER LEADS 1986

1 *	2	3	4	5	6	7	8	9
DOWN MAIN DISTANT — 2 3 4	DOWN MAIN HOME	DOWN MAIN STARTING	DOWN MAIN ADVANCED STARTING					
10 *	11 *	12	13	14	15	16	17 *	18
DISC AT 11 — NIL OR 11	DOWN MAIN — SPUR	DISC FOR 11 — 11	DISC FOR 15 — 15	DISC AT 16B (SELECTED) NIL OR 16	MAIN — TO CROSS	DISC DOWN MAIN TO UP MAIN — 15	DISC DOWN SIDING STARTING TO SPUR	
19	20	21	22	23	24	25	26 *	27
		DISC FOR NO. 22 — 22	DOWN MAIN — DOWN SIDINGS	DISC AT 22 — NIL OR 22		UP MAIN ADVANCED STARTING	UP MAIN STARTING	UP MAIN HOME
28			1	2				
UP MAIN DISTANT — 27 26 25			DOWN MAIN DETONATORS OFF — ON	DETONATORS OFF — ON				

* Ivorine Lead

Source B.B.
Visit 29.5.86