

WEARDE

1953

1	2	3			6
UP MAIN DISTANT	UP MAIN HOME	UP MAIN STARTING			UP MAIN DETONATORS
3 2		LINE CLEAR			
7	8	9	10	11	12
DISC FOR No 8	UP MAIN  DOWN SIDINGS	DISC FOR No 10	MAIN  TO CROSS	DISC FOR No 10	DISC FOR No 13
10 8	10	10		10 OR 10 8	13
13	14	15	17	18	19
DOWN MAIN  DOWN GOODS RUNNING LOOP	DOWN GOODS RUNNING LOOP STARTING  13	DOWN MAIN DETONATORS  OFF  ON	DOWN MAIN STARTING  LINE CLEAR	DOWN MAIN HOME	DOWN MAIN DISTANTS  17 16