

SER-IAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			CLOSURE OF WYESHAM JCN S.B. BRANCH DISTANT NO LONGER LOWER ARM. ETS SECTION EXTENDED TO REDBROOK	1.1.1917
431			ADDITIONAL BRANCH HOME PROVIDED, NUMBERED 36. EXISTING NOS 34.35.36 RENUMBERED 33.34.35. UP BRANCH DISTANT RENEWED AT 1983*	18.9.1925
467			CLOSURE OF REDBROOK S.B. E.T. TABLET TO ST. BRIAVELS REPLACED BY E.T. STAFF.	11.1.1927
			YELLOW ARMS & LIGHTS FOR DISTANT SIGNALS	
433			CLOSURE OF ST. BRIAVELS S.B. E.T.S. TO TINTERN	21.11.1928
1961			CLOSURE OF DINGESTOW S.B. E.T.S. TO LLANDENNY	19.6.1931
1990			DOWN STARTINGS RENEWED	1.7.1931
91			UP MAIN HOME REPOSITIONED FROM 370x TO 430x. UP MAIN DISTANT REPOSITIONED 156x FURTHER OUT	10 & 11 3.1932
			SIGNAL No.4 REPOSITIONED AT 421x	
			E.T. TOKEN TO LLANDENNY 1/40 E.T.S.	
				C. 1951
A	6.55		UP MAIN INNER HOMES RENEWED WITH STANDARD ARMS 1/40 CENTRE PIVOT	

ISSUE 2

MONMOUTH TROY

RECORD OF AMENDMENTS

S2498 /1/1