

SERIAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			DOWN DETONATOR PROVIDED. (ORDERED 16.2.1910)	1910
			2T PROVIDED	(1915-18)

WHITLAND WEST

RECORD OF AMENDMENTS

S2052 /1/1

SER- IAL	DWGS DATE	PLAN No.	DETAILS	OCC'N
			UP BAY BACKING R.I. SIGNAL RENEWED	*
			DOWN MAIN ADV'D STARTING RENEWED	*
			UP MAIN INNER HOMES RENEWED	c. 1948
			SIGNAL 9A RENEWED.	c. 1960
			DOWN BAY STARTINGS (3/7) RENEWED AS DOOBLE DISC. (BRACKET BLOWN DOWN)	c 62
			22T ADDED 1/40 FPL BAR	c 62
			UP MAIN DISTANT RENEWED	*
			DOWN ^{UP} MAIN DETONATOR PROVIDED. SMALL 1-LEVER FRAME REPLACED BY 2 LEVER.	65
			UP BRANCA HOMES & INNER HOMES RENEWED IN NEW FORM. (No.10 NOW DISC)	5. 9. 65
			POINTS 13, FPL 14, SIGNALS 35.36.37.41.8 RECOVERED.	26.6.66
			LOCKING CONVERTED TO V.T. 5 BAR	66
			SLIP CONNECTION TO FIELD SIDINGS, SIDINGS & G.F. RECOVERED	1.67
			MAINS X OVER RECOVERED.	72.

WHITLAND WEST

RECORD OF AMENDMENTS

S2052 11/2