

SERIAL	DWGS DATE	PLAN No.	DETAILS	OCCN
A	2.54		AR.LR. PROVIDED FOR DISC No. 27.	
B	4.54		BRACKET SIGNALS 4&5, 66, 68, 73, 77 RENEWED & ALTERED	
C	7.54		DOWN MAIN & RELIEF DISTANTS RENEWED & REPOSITIONED	
D	9.56		S.WALES FORGE MASTERS SIDING RECOVERED	
E			SIGNALS 7.8.65.67.68.7 <del>B</del> RENEWED	28.8.60
F	2.60		16.17.21 ELNS PROVIDED	
G	5.60		SIGNAL No. 9 REPOSITIONED	
H			ALTERATIONS i/d/w RECOVERY OF PENTYRCH XING S.B.	X
J	7.64		BLOCK WORKING TO NANTGARW RECOVERED	
K	8.64		LOCKING ALTN i/d/w DMS LETTER OF 2.6.64	
L			PERMISSIVE BLOCK TO TREForest ADDED	4.10.64.
M	10.64		i/d/w DEMOLITION OF PENTYRCH XING S.B.	
N			i/d/w RECOVERY OF ROCKWOOD S.B.	8.11.64
O			RELIEF LINES TO TREForest JCN RENAMED GOODS	20 } 27 } 6.65
P			UP GOODS TO WAREHOUSE SIDING CONNECTION RECOVERED i/d/w COAL CONCENTRATION DEPOT	11.7.66

WALNUT TREE JCN

RECORD OF AMENDMENTS

S1402 / / /

SERIAL	DWGS DATE	PLAN No.	DETAILS	OCCN
Q			HAND WORKED CONNECTION IN GARTH SIDING, TRAP POINT IN YARD SIDING, H.P. & SPRING POINT IN SIDING LEADING TO SAND DRAG & ASSOCIATED DISC RECOVERED	11.7.66
R	10.66		RESISTOR ADDED TO UP B&H BLOCK 1/c/w NEW SWITCH AT PENRHOS JCN	
S			BRANCH + OVER, S.WALES FORGE MASTERS SDG & ASSOCIATED DISCS RECOVERED.	24.2.67.
T			1/c/w RECOVERY OF PENRHOS JCN S.B. LOCKING REMOVED FROM C/POINT 47.	29.1.68
U	4.68		AR. LR. PROVIDED FOR SIGNALS 69 & 78. INTERLINKING MODIFIED.	
V	9.69		RED FLASHING LIGHTS PROVIDED AT CWS XING.	
W	10.69		ADDITIONAL JR IN FLASHING LIGHT CIRCUITS	
X			DOWN GOODS FROM TREForest TAKEN OUT OF USE.	26.4.70.
Y	4.71	SP 65/55	LOCKING ALT'N 1/c/w RECOVERIES (SERIAL X)	
Z		SP 72/50	SINGLING OF NANTGARW BRANCH	25.11.73.
AA		SP 73/54	REMODELLING AT SOUTH END	3.74
AB			UP MAIN & UP GOODS DISTANTS MADE C/LIGHT	9.74
AC			UP GOODS LOOP TO MAESMAWR & UP SIDINGS RECOVERED. UP GOODS HOME & STARTING RECOVERED.	7.8.78.
AE	881		T.C. INTERRUPTER PROVIDED IN 57T	
AF		SP 82/113	UP GOODS CLOSED.	
AG	787	*	B&H & DGL RECOV. 440x OIL ON DM HOME * SP86/27A & 87/20A	
AH			RTCKs changed	16.3.87
AJ			Mod to dunes indication ckt	26.3.89
AK	7.91	SP 91/9	CWS xing removed. Nantgarw b&h bolted	

WALNUT TREE JCN

RECORD OF AMENDMENTS

SI402 / 1 / 2