

# PWLLYRHEBOG

①

2  
DOWN  
MAIN  
HOME

3  
DOWN  
MAIN  
STARTING

4  
DOWN  
MAIN  
ADVANCED  
STARTING

5

6  
WAREHOUSE  
SIDING  
—  
UP  
MAIN

8  
DISC  
FOR  
NO 6  
—  
6

9  
DOWN  
RELIEF  
DISTANTS  
—  
12  
11  
10

10  
DOWN  
RELIEF  
HOME

11  
DOWN  
RELIEF  
STARTING

12  
DOWN  
RELIEF  
ADVANCED  
STARTING

14  
DISC  
FOR  
NO 15  
—  
15

15  
WAREHOUSE  
SIDING  
(UPPER)  
—  
DOWN  
MAIN

16  
DISC  
FOR  
NO 15  
—  
15  
OR  
6  
15  
8

17  
DISC  
FOR  
NO 21  
—  
24  
21

18  
DISC  
FOR  
NO 21  
—  
25  
21

20

21  
COMPOUND  
POINTS

22  
DISC  
FOR  
NO 24  
—  
24

23  
DISC  
FOR  
NO 24  
—  
25  
24

24  
UP  
MAIN  
AND  
DOWN  
RELIEF  
—  
TO  
CROSS

26

27  
SPRING  
POINTS  
IN  
UP  
MAIN  
(SLOTTED)

28

29  
DISC  
FOR  
NO 24  
—  
24  
—  
OR  
31  
24

30

31  
?  
(TORN)  
—  
25  
—  
OR  
21  
25

32  
DISC  
AT  
NO 27  
—  
33  
41

33  
SAFETY  
POINTS  
IN  
UP  
RELIEF

34  
DISC  
FOR  
NO 38  
—  
38  
37

35  
DISC  
FOR  
NO 38  
—  
38

NOTE: NOS 1, 7, 13, 19, 25 TORN OFF K.S.

PWLLYRHEBOG

<u>36</u> DISC FOR NO 37 — 38 37	<u>37</u> WAREHOUSE SIDING (LOWER) — DOWN RELIEF — 38	<u>38</u> WAREHOUSE SIDING (LOWER) — DOWN MAIN	<u>39</u> DISC FOR NO 38 — 38	<u>40</u> UP RELIEF — UP MAIN — 33	<u>41</u> SAFETY POINTS IN SIDINGS — 33
--	---	--	--	---	---

<u>42</u> DISC FOR NO 33 — 33	<u>43</u> DISC FOR NO 41 — 33 41 42	<u>44</u> UP MAIN STARTING	<u>45</u> UP RELIEF HOME — 33 40 42	<u>46</u> UP MAIN HOME	<u>47</u> —	<u>48</u> UP MAIN DISTANT — 44 46
--	--	-------------------------------------	--	---------------------------------	----------------	---

FOR INSPECTOR POWELL  
CARDIFF  
CHARGE TO MAINTENANCE  
SUPPLY WITH LOCKING MATERIAL

NOV. 9. 1927

---

<u>33</u> SIDING SAFETY & FALLING BAR IN UP MAIN	<u>40</u> DISC FOR NO 33 — 33	<u>41</u> UP MAIN — UP RELIEF	(42)	(43)	<u>45</u> UP MAIN INNER HOME	<u>47</u> UP MAIN HOME	<u>48</u> UP MAIN DISTANT — 44 45 47
--	--	--	------	------	--	---------------------------------	---

FOR INSP. SEABOURNE  
TREForest  
ORDER NO 2737

18/8/31

PART OF NO 32 VICE  
NO 46 TURN OFF  
K.S.

PWLLYRHE BOG

48

UP  
MAIN  
DUTANT

ORDER NO 29/9748

IVORINE WITH CASTING REQUIRED

44

45  
47

MR BENNETT  
TREForest

21. MAR. 1966

43

UP  
MAIN  
ADVANCED  
STARTING

48

UP  
MAIN  
DUTANT

2 NEW LEADS

IVORINES & CASTINGS

ORDER NO 40/5066.

47

45

44

43

MR. NORRIS

TREForest

6. NOV. 1953