

SERIAL	DRGS DATE	PLAN No.	DETAILS	OCC'N
			NEW LOCKING FRAME	1913
			DOWN MAIN SHUNT No.15 ADDED	7.1915
			LOCKING ALTERATION : LOCKING BETWEEN POINTS EASED.	c. 2.1916
			DISC No.13 ADDED.	20.3.1917
	3.1926		COLLIERY SIDING & SIGNALLING RECOVERED. Nos. 18.19.20 MADE SPARE	

CWM GLYN

RECORD OF AMENDMENTS

S

/1