BRITISH RAILWAYS

(WESTERN REGION)

(For the use of employees only)

Notice to Trainmen, etc.

MULTIPLE ASPECT SIGNALLING

OLD OAK COMMON

SATURDAY, 11th DECEMBER to MONDAY, 13th DECEMBER, 1971

Between the hours of 22.00 on Saturday, 11th December and 06.00 on Monday, 13th December, 1971 (or until completion) the Divisional S. & T. Engineer will be engaged in alterations to signalling in connection with remodelling of the layout at the West Junction.

IMPORTANT

STATION AND DEPOT SUPERVISORS must acknowledge receipt of this Notice by the return of the attached slip.

Received Notice 1.XO.122 re Multiple Aspe	ct Signalling alterations at Old Oak Common.
Date	Department
Station	Signature
B)	

Divisional Manager (London), Western Tower, Reading

SIGNALLING RECORD SOCIETY

<u>www.s-r-s.org.uk</u> DIGITAL ARCHIVE

This PDF Copy has been provided free of charge by David Allen in order to assist your research into UK signalling.

This file is one of a number scanned by David Allen using material from his own collection and from the collections of Peter Barlow, Phil Deaves, Robert Dey, David Ingham, Simon Lowe, Richard Maund, John McCrickard, John Midcalf, Richard Pulleyn, Roger Newman and Chris Wolstenholmes. Thank you one and all. Many of the original documents are now in the SRS Archive or at the National Railway Museum.

You may also like to provide copies of Signalling Notices and Weekly (and periodical) Operating Notices or other notices as scans or as originals. The SRS is always willing to accept donations of any signalling or signalling related material for inclusion in the Society's Archive. Please contact the Archivist in the first instance.

For a list of PDFs currently available visit the <u>Archives</u> pages of the SRS Web Site.

If you have benefited from this PDF copy, why not join the Signalling Record Society and receive support for your researches and access to the Society's Archives

Members receive "The Signalling Record" six times annually plus a newsletter and have the opportunity to purchase SRS <u>books</u> and other <u>publications</u> at a discount. They also have access to back issues of The Newsletter and The Signalling Record which are only available to members. These contain a wealth of information accumulated since 1970, much of which is not readily available anywhere else.

In addition, Members have the opportunity to join signalling related visits to locations on the UK national and London Underground systems; and to other UK Railways.

To join the Signalling Record Society visit

www.s-r-s.org.uk/membform.html

OLD OAK COMMON (FIELD SIDINGS)

I. THE FOLLOWING LINES WILL BE RENAMED:-

Existing

Down Yard Line

Up Yard Line

Up Siding Line

To Become

Down Reception Line

Up Reception No. 1 Line

Up Reception No. 2 Line

2. PERMANENT WAY ALTERATIONS

The following connections will be spiked, clipped and padlocked out of use pending recovery:—

The trailing crossover in the Down and Up Yard Line and the Up Yard to Up Siding facing and trailing connections.

New permanent way will be brought into use as shown on the attached diagram.

N.B. The lines shown on the attached diagram as Down Through, Up Through No. I and Up Through No. 2 will in future be known as the DOWN RECEPTION, UP RECEPTION No. I and UP RECEPTION No. 2 respectively.

3. SIGNALLING ALTERATIONS

Signalling alterations will be carried out as follows:-

The existing Down Yard Ground Frame will be taken out of use together with the associated stop boards in the Down Yard, Up Yard and Up Siding lines.

The route indicators on signals 00.241, 00.341 and 00.541 will all be taken out of use.

Ground Position Light signal 00.492 at the west end of the Up Siding will be taken out of use.

Ground Position Light signal 00.561 will be repositioned to the rear of the new connection in the Up Reception No. 2 Line and Ground Position Light signal 00.571 will be repositioned to the rear of the new connection from Up Reception No. 2 Line to Up Reception No. 1 Line as shown on the attached diagram.

On the following signals, routes, which previously gave access as far as the Down Yard Stop Board, will now give access as far as the Ground Position Light signal 00.488 on the Down Reception Line:— 00.478 (A), 00.466 (A), 00.366 (D), 00.472 (C), 00.16 (C), 00.480 (C) and 00.116 (C).

On the following signals, routes, which previously gave access as far as the Up Yard Stop Board, will now give access as far as Ground Position Light signal 00.490 on the Up Reception No. I Line:—

00.366 (E), 00.472 (D), 00.16 (D), 00.480 (D), 00.116 (D), 00.478 (B), 00.466 (B) and 00.468 (A).

On the following signals new routes will be brought into use:-

00.366 (F), 00.472 (E), 00.16 (E), 00.480 (E), 00.116 (E), 00.478 (C), 00.466 (C) and 00.468 (B).

These new routes will give access as far as Ground Position Light signal 00.484 in the Up Reception No. 2 Line.

The Ground Position Light signals, 00.563, 00.569 and 00.484 shown on the attached diagram will be brought into use.

4. TRACK CIRCUITS

The Down Reception, Up Reception No. 1 and Up Reception No. 2 Lines will be fully track circuited.

5. POWER OPERATED POINTS

The new connections, 717 and 718 will be motor worked from Old Oak Common Signal Box. The point machines will be of the GRS 5A type, for which the instructions for emergency operation have been separately issued.

6. OCCUPATION ARRANGEMENTS

Occupation of the signalling panel will be required for the purpose of altering and testing the interlocking.


During the occupation, signals 00.141, 00.241 and 00.341 will display restricted Aspects.

All arrangements for the safe working of the line will be made by the nominated person in charge of the possession in accordance with Rule 218A. Any Handsignalmen required in accordance with Rule 77 will be appointed by the District Inspector, Old Oak Common.

H. N. TODD,

Divisional Manager, READING.

December, 1971



OLD OAK COMMON (FIELD SIDINGS)