Opening of New Signal Box Alteration of Signals Sandford and Banwell.

Commencing at 7.0 a.m. on Tuesday, December 12th, 1905, a New GOODS LOOP Siding and a New Signal Box on the Up Side of the Loop will be brought into use, as well as the undermentioned New Signals:—

(NOTE.—The Goods Loop must only be used for Goods trains to cross a Goods train or a Passenger train, and two Passenger trains must not cross each other at this Station.)

Form	Description.	Position.	Distance from Box.
2	1. Down Main Home (already in use) 2. Down Main to Loop Home	Down Side of Line	220 yds.
	Down Main Platform Starting	Down Side of Line	22 y ds.
	Down Main Starting	Down Side of Line	131 yds.

SIGNALLING RECORD SOCIETY

<u>www.s-r-s.org.uk</u> DIGITAL ARCHIVE

This PDF Copy has been provided free of charge by David Allen in order to assist your research into UK signalling.

This file is one of a number scanned by David Allen using material from his own collection and from the collections of Phil Deaves, Robert Dey, David Ingham, Simon Lowe, John McCrickard, John Midcalf, Roger Newman, Richard Pulleyn and Chris Wolstenholmes. Thank you one and all. Many of the original documents are now in the SRS Archive or at the National Railway Museum.

You may also like to provide copies of Signalling Notices and Weekly (and periodical) Operating Notices as scans or as originals. The SRS is always willing to accept donations of any signalling or signalling related material for inclusion in the Society's Archive. Please contact the Archivist in the first instance.

For a list of PDFs currently available visit the list of <u>Weekly</u> Notices or <u>Signalling</u> Notices page.

If you have benefited from this PDF copy, why not join the Signalling Record Society and receive support for your researches and access to the Society's Archives

Members receive "The Signalling Record" six times annually plus a newsletter and have the opportunity to purchase SRS <u>books</u> and other <u>publications</u> at a discount. They also have access to back issues of The Newsletter and The Signalling Record which are only available to members. These contain a wealth of information accumulated since 1970, much of which is not readily available anywhere else.

In addition, Members have the opportunity to join signalling related visits to locations on the UK national and London Underground systems; and to other UK Railways.

To join the Signalling Record Society visit

www.s-r-s.org.uk/membform.html

one of a color	Down Main Advanced Starting	Down Side of Line	350 yds.
	Loop to Down Main Starting	Outside Loop Line	131 yds.
<u>:::</u> ·.			, *
· · <u>·</u>			
	Loop to Up Main Starting	Up Side of Loop	138 yds.
	•	- Andrew	
	Up Main Advanced Starting	Up Side of Line	350 yds.
		:	
1			
2	1. Up Main Home (already in use)	Up Side of Line	280 yds.
	2. Up Main to Loop Home		

At the same time the ground frame working the Up facing points and facing point lock and the New Goods Loop will be brought into use.

The telegraph apparatus in the Existing Signal Box will be transferred to

the New Box.

The Existing Signal Box will be taken out of use. Discs will be fixed at the points leading from Sidings and at the points of the Crossover Road.

Whilst the work is being carried out, the Distant Signals affected will be disconnected and placed at danger.

Daniel of Street, Stre	Down Main Advanced Starting	Down Side of Line	350 yds.
	Loop to Down Main	Outside Loop Line	131 yds.
			, .
	Loop to Up Main Starting	Up Side of Loop	138 yds.
	•		
	Up Main Advanced Starting	Up Side of Line	350 yds.
		:	
2	1. Up Main Home (already in use)	Up Side of Line	280 yds.
	2. Up Main to Loop Home		

At the same time the ground frame working the Up facing points and facing point lock and the New Goods Loop will be brought into use.

The telegraph apparatus in the Existing Signal Box will be transferred to the New Box.

The Existing Signal Box will be taken out of use.

Discs will be fixed at the points leading from Sidings and at the points of the Crossover Road.

Crossover Road.

Whilst the work is being carried out, the Distant Signals affected will be disconnected and placed at danger.

During the time the work is in hand Distant signals Nos. 1 and or will be disconnected and placed at danger.

Thursday, December 14th, 1905.

Commencing at 7.0 a.m. the Up Distant Signal will be moved to a new position 1290 yards from the Box, on the Up side of the Line.

During the time the work is in hand Distant Signals Nos. 1 and 31 will be disconnected and placed at danger.

On each of these dates—December 12th, 13th and 14th—Inspector Fawden must make all arrangements for the safe working of the Line, including the appointment of groundmen, in accordance with Rule 71 of the Book of Rules.

Advise all concerned and acknowledge receipt to Head of Department.

C. KISLINGBURY,

Divisional Superintendent.

TEMPLE MEADS STATION,

Bristol, December 5th, 1905.

Arrowsmith, Printer, Quay Street, Bristol.