GREAT WESTERN RAILWAY.

(For the use of the Company's servants only.)

BADMINTON-NEW GOODS LOOP

On Sunday, 20th July, 1941, between the hours of 7.0 a.m. and 6.0 p.m. or until the work is completed, the Signal Engineer will be engaged in bringing into use extensions to Down and Up Loop Lines as shewn in sketch and the following new signals:—

Description.	Position.	from Box.
Up Goods Loop to Up Main Starting.	Up side of Up Goods Loop.	343 yards.
	and the Control of the	
Down Platform Line Inner Home.	Down side of Down Plat- form Line.	69 yards.
	101	
Down Main Inner Home.	Between Down Main and Down Platform Line.	69 yards.
	Main Starting. Down Platform Line Inner Home.	Down Platform Line Inner Home. Down side of Down Platform Line. Down Main Inner Home. Between Down Main and Down Platform Line.

The existing Up Main Advanced Starting Signal will be moved 305 yards farther from the box on the Up side of the line; no alteration in height or form.

The following track circuits will be brought into use:

Track Circuit in rear of Signal named below.	Length of Track,	Position of Train Waiting Indicator.
Up Goods Loop. Up Goods Loop to Up Main Starting. Through Points 47.	150 yards. 49 yards.	Up Goods Loop to Up Main Starting.

SIGNALLING RECORD SOCIETY

<u>www.s-r-s.org.uk</u> DIGITAL ARCHIVE

This PDF Copy has been provided free of charge by David Allen in order to assist your research into UK signalling.

This file is one of a number scanned by David Allen using material from his own collection and from the collections of Phil Deaves, Robert Dey, David Ingham, Simon Lowe, John McCrickard, John Midcalf, Roger Newman, Richard Pulleyn and Chris Wolstenholmes. Thank you one and all. Many of the original documents are now in the SRS Archive or at the National Railway Museum.

You may also like to provide copies of Signalling Notices and Weekly (and periodical) Operating Notices as scans or as originals. The SRS is always willing to accept donations of any signalling or signalling related material for inclusion in the Society's Archive. Please contact the Archivist in the first instance.

For a list of PDFs currently available visit the list of <u>Weekly</u> Notices or <u>Signalling</u> Notices page.

If you have benefited from this PDF copy, why not join the Signalling Record Society and receive support for your researches and access to the Society's Archives

Members receive "The Signalling Record" six times annually plus a newsletter and have the opportunity to purchase SRS <u>books</u> and other <u>publications</u> at a discount. They also have access to back issues of The Newsletter and The Signalling Record which are only available to members. These contain a wealth of information accumulated since 1970, much of which is not readily available anywhere else.

In addition, Members have the opportunity to join signalling related visits to locations on the UK national and London Underground systems; and to other UK Railways.

To join the Signalling Record Society visit

www.s-r-s.org.uk/membform.html

Track Circuit in rear of Signal named below.	Length of Track.	Position of Train Waiting Indicator.
Up Main. Advanced Starting.	300 yards.	Up Advanced Starting.
Through Points 47.	143 yards.	-
Down Main. Through Points 38.	125 yards.	

Inspector Old to make arrangements for safe working in accordance with Rule 77 and provide the necessary handsignalmen.

ACKNOWLEDGE RECEIPT TO HEAD OF DEPARTMENT.

Temple Meads Station, Bristol, July, 1941. R. G. POLE, Superintendent of the Bristol Division.

Received Notice S.1887, re Signal Alterations, etc., Badminton.

Department.

Station.

Signature.

Mr. R. G. POLE,
Divisional Superintendent's Office,
Bristol.

BADMINTON

