

SW

SCOTTISH REGION

No.38

WEEKLY OPERATING NOTICE

CONTAINING

TEMPORARY SPEED RESTRICTIONS

TEMPORARY ENGINEERING WORKS

SIGNALLING AND PERMANENT WAY ALTERATIONS

GENERAL INSTRUCTIONS AND NOTICES

SATURDAY 19 SEPTEMBER

TO

FRIDAY 25 SEPTEMBER 1981

INCLUSIVE

Trainmen must pay particular attention to works contained in this Notice and keep a good look-out for handsignals, which may be exhibited in accordance with the Rules and Regulations.

Work at places other than those mentioned may be in progress and Drivers must be on the look-out and be prepared to stop or run at reduced speed when, and where, handsignals may be exhibited.

Receipt of this Notice need not be acknowledged. If not received by 17 00 Thursday advise CHIEF OPERATING MANAGER, extension 041-3666 using the railway network where possible, otherwise Post Office 041-332-9811, extension 3666.

SIGNALLING RECORD SOCIETY

www.s-r-s.org.uk

This PDF Copy has been provided free of charge by David Allen in order to assist your research into UK signalling.

This file is one of a number scanned by David Allen using material from his own collection and from the collections of Phil Deaves, Robert Dey, David Ingham, Simon Lowe, John McCrickard, John Midcalf, Roger Newman, Richard Pulleyn and Chris Wolstenholmes. Thank you one and all. Many of the original documents are now in the SRS Archive or at the National Railway Museum.

You may also like to provide copies of Signalling Notices and Weekly (and periodical) Operating Notices as scans or as originals. The SRS is always willing to accept donations of any signalling or signalling related material for inclusion in the Society's Archive. Please contact the <u>Archivist</u> in the first instance.

For a list of PDFs currently available visit the list of <u>Weekly</u> Notices or <u>Signalling</u> Notices page.

If you have benefited from this PDF copy, why not join the Signalling Record Society and receive support for your researches and access to the Society's Archives

Members receive "The Signalling Record" six times annually plus a newsletter and have the opportunity to purchase SRS <u>books</u> and other <u>publications</u> at a discount. They also have access to back issues of The Newsletter and The Signalling Record which are only available to members. These contain a wealth of information accumulated since 1970, much of which is not readily available anywhere else.

In addition, Members have the opportunity to join signalling related visits to locations on the UK national and London Underground systems; and to other UK Railways.

To join the Signalling Record Society visit

www.s-r-s.org.uk/membform.html

WATCH OUT !! A.P.T. ABOUT

BETWEEN CARLISLE AND GLASGOW CENTRAL VIA BEATTOCK

An additional A.P.T. is now being commissioned and testing with the trains is continuing on the Carlisle/Glasgow Central via Beattock line at speeds up to 125m.p.h.

Staff must anticipate high speed running at all times.

Staff must also exercise the utmost vigilance when walking the track and observe the provisions of the "Safety Code for Track Walking" (BR2999/12).

Attention is specially drawn to the reduced time which will be available from staff sighting an APT and clearing to a point of safety.

A place of safety is one which will allow 2.5m. (8' 3'') clearance from the track.

If unable to reach a place of safety in time staff must lie down in the cess.

In areas of limited clearance the following additional safeguards are provided:-

- Where refuges are not provided, the extent of limited clearance will be denoted by blue and white chequered plate lettered "Warning - No Refuges." 1)
- Where clearance is limited on both sides of the line, refuges or handrails are normally provided, at 40 metre intervals, on both sides of the line, and these are 2) staggered to give 20 metres between successive refuges.
- Where clearance is limited on one side of the line only, staff must take refuge on 31 the opposite side.
- In rock cuttings refuges will be marked in white paint.
- At certain overbridges/viaducts where refuges are not provided, an audible 4) warning system is installed to give adequate advice of the approach of trains to enable staff to proceed to a point of safety. The midway point of these locations is 5) marked to assist staff in deciding the nearest exit point. The instructions for operating the warning system are detailed in Page 214 of the Sectional Appendix.
- At station platforms, step irons are provided on the platform faces at the same 6) spacing as for refuges.
- On platform surfaces a yellow line is painted with associated warning notices displayed instructing people to stay behind the yellow line clear of the platform 7) edge.
- (MR/D1086/P) (Amended 26/1/80) Trackside location cases are fitted with handrails. 8)

SW-2

At	or between	Lines affected	Remarks
CR	AIGENDORAN JN. TO	FORT WILLIAM - continu	Jed
MO	NDAY 21 to WEDNESD	AY 23 SEPTEMBER	
227	Arrochar & Tarbet and Ardlui	Single BLOCKED	21 00 Mon and Tue to 06 45 Tue and Wed. Track maintenance between 19m. 45ch. and 27m. 48ch.
WE	DNESDAY 23 and THUR	SDAY 24 SEPTEMBER	
228	Ardlui and Crianlarich	Single BLOCKED	21 00 Wed to 07 00 Thu. Track maintenance between 27m. 48ch. and 36m. 25ch.
MAI	LLAIG JN. TO MALLAI	G	
SUI	NDAY 20 SEPTEMBER		
229	Arisaig and Mallaig	Single BLOCKED	07 30 to 16 30. Track renewal between 32m. 60ch. and 33m. 10ch.

SECTION C

SIGNALLING AND PERMANENT WAY ALTERATIONS

** Indicates items which will not appear in future issues and which must be noted

BETWEEN LOCKERBIE STATION AND WAMPHRAY G.F. - Nethercleugh level crossing has been closed, all associated equipment removed and the roadway fenced off. (39)

DETAILS OF WORK REFERRED TO IN SECTION B

NIL

DETAILS OF WORK ALREADY CARRIED OUT

MIDCALDER JUNCTION – The bracket post carrying the Up from Edinburgh line home signals has been renewed as two separate straight posts, 2 yards farther from the box, application unaltered signs have been affixed to both posts.

BETWEEN MUIRHOUSE CENTRAL JUNCTION AND MUIRHOUSE SOUTH JUNCTION – The loco siding, exit signal G618 and associated trailing connection from the Up Barrhead line have been secured out of use pending removal.

The route indicator associated with position light signal, G614 has been removed and the signal repositioned 50 yards nearer Muirhouse Central Junction. The application of this signal now applies back along Up Barrhead line. (40)

SW-26

SECTION C - SIGNALLING AND PERMANENT WAY ALTERATIONS - continued

DETAILS OF WORK ALREADY CARRIED OUT - continued

REMOVAL OF CATCH POINTS -

The catch points listed below have been secured out of use pending removal :-

Sectional Appendi Page No. 41/42	x Located at/between Barrhead and Lugton	Line Up	Mileage/Location 7m. 09ch.
45	Clarkston and Stamperland and Busby	Up	680 yards before reaching signal G664
			100 yards after passing signal G664.
51	Girvan	Up	208 yards after passing home signal.
51	Kilkerran	Down loop	35 yards after passing starting signal. (39)

SECTION D

GENERAL INSTRUCTIONS AND NOTICES

* Indicates item included for the first time

** Indicates item which will not appear in future issues and which must be noted

WORKING INSTRUCTIONS - CLASS 370 TRAINS (B.R.33076)

Page 2 - Section 2 - MODIFICATIONS TO THE RULE BOOK Add new item.

2.1 Section H, clause 3.7.2

Add (c) If the loud note control becomes defective, the train may continue in service but the maximum speed must be reduced to 100 m.p.h. The defect must be remedied before a subsequent turn is worked.

The existing items 2.1 to 2.5 to be renumbered 2.2 to 2.6.

(22/8/81)

SECTIONAL APPENDIX

CONTENTS

List of lines in the sequence used throughout the book	Page number relating Table "A"
Page 4 - Delete - Pumpherston to Uphall (Goods Line) entry.	(18/7/81)
- Parkhead North Jn. to Haghill Jn. entry.	(9/8/81)

LOCAL INSTRUCTIONS

INDEX

Page 7 Add - Curriehill

Page 8 - Delete - Kingsknowe entry.

Page 221

(29/8/81) (29/8/81)

CARELESSNESS COSTS CASH

VEHICLES DAMAGED THROUGH CARELESS

SHUNTING MEANS LARGE REPAIR BILLS

DAMAGE IS BEING CAUSED TO -

(i) GANGWAYS AND JUMPER CABLES NOT DISCONNECTED WHEN COACHES ARE UNCOUPLED

(ii) COACHES LEFT FOULING POINTS AND CONNECTIONS IN SIDINGS

LOSS OF VEHICLES

MEANS

LOSS OF REVENUE

MEANS

NO MONEY FOR REPAIRS

BE CAREFUL WHEN SHUNTING